



(206) 753-6884

EXTREMELY HAZARDOUS WASTE MANIFEST
Required by WAC 173-302

USEPA SF



1473580

1 GENERATOR * Scott Galvanizing Co.ADDRESS 1520 N W Leary WayE.I.N.** [REDACTED]WASTE ORIGIN SamePHONE 778 783-3100

(If different from address above)

WASTE DESCRIPTION (including hazardous constituents and range of concentration)	QUANTITY	CONTAINER	BULK SHIPMENTS		
			GAL.	LB.	CU.FT.
Sulfuric Acid Waste w/ traces of Zinc	23 2400	Bulk			
PHI					

DOT SHIPPING NAME Scott Galvanizing Co.

DOT HAZARD CLASS _____

PHYSICAL STATE (CIRCLE): SOLID LIQUID SLUDGE OTHER _____MAJOR HAZARD (CIRCLE): TOXIC CORROSIVE IGNITABLE REACTIVE OTHER _____

SPELL/SPECIAL INSTRUCTIONS _____ (Describe)

IN THE EVENT OF A SPILL, CONTACT EITHER THE DEPARTMENT OF ECOLOGY (see 24 hr. nos. on reverse) or THE NATIONAL RESPONSE CENTER, U.S. COAST GUARD 800-424-8802 FOR EMERGENCY ASSISTANCE.

This is to certify that the above-named materials are properly classified, described, packaged, marked, labeled and are in proper condition for transportation according to the applicable regulations of the U.S. Department of Transportation. Signed and dated by the authorized agent of the generator:

GENERATOR SIGNATURE [Signature] DATE 12/10/802 COLLECTION SITE Scott Galvanizing Co.E.I.N.** [REDACTED]ADDRESS 1520 NW Leary WayPHONE 783-3100Seattle, Wa. 981073 TRANSPORTER [Signature]E.I.N.** [REDACTED]

ADDRESS _____

PHONE 284-2950TRANSPORTER SIGNATURE [Signature]DATE 12-10-804 TREATMENT OR DISPOSAL SITE Western Processing CoE.I.N. [REDACTED]ADDRESS 7215 South 196thPHONE 872-4078TREATMENT/DISPOSER SIGNATURE [Signature]DATE 12-11-80

* Generator should also complete parts 2, 3 and 4, except for signatures.

** EIN is the IRS employer identification number.

Distribution: Generator: Goldenrod copy, Transporter: Pink copy, Treater/Disposer: Canary copy

(T/D returns original to Generator)